

# Final Reclamation and Stormwater Inspection

February 13, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 336107

Inspection Document #: 674902574

Weld County, CO

SENE Section 16 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CRESTONE PEAK RESOURCES /1N65W31  
Location ID: 336107



**Photo 1.** Photo taken from the location, facing Southeast. Appears the Operator has removed all well equipment from the P&A well.



**Photo 2.** Photo taken from the access road off CR 2, facing South. See comments from Photo 1.