

Inspection Photo (s)
North Bank E-1
API # 05-045-11777
Inspection # 689303261



Location Photo #1



Location Photo #2

Inspection Photo (s)
North Bank E-1
API # 05-045-11777
Inspection # 689303261



**Location Photo #3, condensate in drip pan,
stained material around drip pan.**



**Location Photo #4, Stained material around
drip pan.**

Inspection Photo (s)
North Bank E-1
API # 05-045-11777
Inspection # 689303261



Location Photo #5, Condensate in drip pan.