

Inspection Photo (s)
North Bank B-1
API # 05-045-10909
Inspection # 689303267



Location Photo #1



Location Photo #2

Inspection Photo (s)
North Bank B-1
API # 05-045-10909
Inspection # 689303267



Location Photo #3



**Location Photo #4, Stained material separator
at blowdown line.**

Inspection Photo (s)
North Bank B-1
API # 05-045-10909
Inspection # 689303267



Location Photo #5, Stained material separator at blowdown line.



Location Photo #6, Stained material separator at blowdown line.