

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401555646
Date Received:
02/26/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 26625
Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-9362
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Archuleta, Amy</u>		<u>aarchuleta@elmridge.net</u>
<u>James Rackler</u>		<u>jrackler@elmridge.net</u>
<u>Lindeman, Terry</u>		<u>tlindeman@elmridge.net</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602489
Inspection Date: 02/05/2018 FIR Submit Date: 02/20/2018 FIR Status: _____

Inspected Operator Information:

Company Name: ELM RIDGE EXPLORATION COMPANY LLC Company Number: 26625
Address: 12225 GREENVILLE AVE STE 950
City: DALLAS State: TX Zip: 75243-9362

LOCATION - Location ID: 325440

Location Name: UTE-N33N9W Number: 17NWSW County: LA PLATA
Qtrqr: NWS Sec: 17 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.102670 Longitude: -107.855500

FACILITY - API Number: 05-067- -00 Facility ID: 214777

Facility Name: UTE Number: 2
Qtrqr: NWS Sec: 17 Twp: 33N Range: 9W Meridian: N
W
Latitude: 37.102670 Longitude: -107.855500

CORRECTIVE ACTIONS:

1 ☒ CA# 114512

Corrective Action: Remove riser. Corrective action date will remain November 1, 2017, to document initial corrective action date (with approved extension) and the duration of non-compliance.

Date: 11/01/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: This equipment is not owned or operated by Elm Ridge Exploration. I sent a formal request to Williams Field Services on 8-31-2017. They looked into removing this riser and sent me an email explaining why this can't happen right away. Please see attached email regarding this conversation.

COGCC Decision: **Not Approved**

COGCC Representative: Operator is responsible for removal of equipment after final reclamation. Location will remain out of compliance until riser is removed.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed: _____

Title: Regulatory

Date: 2/26/2018 2:11:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401555646	FIR RESOLUTION SUBMITTED
401555697	Email Correspondence

Total Attach: 2 Files