

Final Reclamation Inspection

February 15, 2019

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

API #: 05-123-07563

Inspection Document #: 682404553

Weld County, CO

SENW Section 31 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CINQUE #3
API #: 05-123-07563



Photo 1. Photo taken 7/28/2014 from the abandoned facility illustrating unused equipment (exposed flowline/piping) submerged in water. A corrective action (CA) inspection was submitted to remove unused equipment, as well as other CA's.

Inspection Photos
Location Name: CINQUE #3
API #: 05-123-07563



Photo 2. Photo taken 3/27/2015 from the abandoned facility illustrating unused equipment (exposed flowline/piping) submerged in water. A second corrective action (CA) inspection was submitted to remove unused equipment, as well as other CA's.

Inspection Photos
Location Name: CINQUE #3
API #: 05-123-07563



Photo 3. Photo taken 2/15/2019 from the from the abandoned facility, facing South. Photo illustrates what appears to be unused equipment (exposed flowline/piping) submerged in water. Does not appear the Operator has removed all equipment from the two previous corrective action inspections.

Inspection Photos
Location Name: CINQUE #3
API #: 05-123-07563



Photo 4. Close-up photo taken 2/15/2019 of the unused equipment (exposed flowline/piping) submerged in water.