

Inspection Photo (s)
Clough RWF 421-23
API # 05-045-12566
Inspection # 689303295



Location Photo #1



Location Photo #2

Inspection Photo (s)
Clough RWF 421-23
API # 05-045-12566
Inspection # 689303295



Location Photo #3



Location Photo #4, unmarked/unused flow line riser.

**Inspection Photo (s)
Clough RWF 421-23
API # 05-045-12566
Inspection # 689303295**



Location Photo #5, Debris behind separators.



Location Photo #6, Debris in between tanks and separators.

Inspection Photo (s)
Clough RWF 421-23
API # 05-045-12566
Inspection # 689303295



Location Photo #7, Debris by fence.

