

Inspection Photos

2/20/2019

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312233

Inspection Doc. Number: 682504521
Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312233



Photo 1: Photo taken from the south end of the well. Photo shows barrels have been placed into secondary containment.



Photo 2: Photo taken from the north end of the well, facing northwest. Photo shows northwest anchor has not been marked in accordance with 1003.a

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312233



Photo 3: Photo taken from the north end of the well, facing northwest. Photo shows northwest anchor has not been marked in accordance with 1003.a