

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2019

Submitted Date:

02/21/2019

Document Number:

692601449**FIELD INSPECTION FORM**
 Loc ID 311257 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300717	WELL	PR	06/24/2010	GW	125-11651	LAMB 07-12	PR

**General Comment:**Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease signs by meter sheds		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Meter sheds and VGS 3/4 fenced with metla panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter sheds		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Kubota gas engine		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Gas scrubber and telemetry equipment at meter sheds		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for Lamb 7-12, 7-14 and Boulders 7-13 690' NW of wellhead		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	300717	Type:	WELL	API Number:	125-11651	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Lamb 7-12, 7-14 and Boulders 7-13) 690' NW of wellhead on E side of CR U								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT