

**SGU 8506D-25 F25496**  
**Api# 05-045-19068**  
**Inspection # 689702681**



**Entrance of location.**



**Battery sign buried in plowed snow bank.**



SGU 8506D-25 F25496  
Api# 05-045-19068  
Inspection # 689702681



**Missing required information. No berm around tank.**



SGU 8506D-25 F25496  
Api# 05-045-19068  
Inspection # 689702681



Missing required information. No berm around tank.



SGU 8506D-25 F25496  
Api# 05-045-19068  
Inspection # 689702681



**Missing required information. No berm around tank.**