

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/21/2019

Submitted Date:

02/21/2019

Document Number:

675001990**FIELD INSPECTION FORM**

Loc ID 334425 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone | Email                                 | Comment                         |
|-----------------|-------|---------------------------------------|---------------------------------|
| Kellerby, Shaun |       | shaun.kellerby@state.co.us            | <a href="#">All Inspections</a> |
| Clark, Chris    |       | cogccnotifications@laramie-energy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 294427      | WELL | PR     | 01/17/2008  | GW         | 077-09476 | VEGA FEDERAL 35-211 | PR          |
| 294670      | WELL | PR     | 02/26/2008  | GW         | 077-09496 | VEGA FEDERAL 35-121 | PR          |
| 294671      | WELL | PR     | 02/26/2008  | GW         | 077-09497 | VEGA FEDERAL 35-214 | PR          |
| 294672      | WELL | PR     | 02/26/2008  | GW         | 077-09498 | VEGA FEDERAL 35-111 | PR          |
| 294673      | WELL | PR     | 12/12/2008  | GW         | 077-09499 | VEGA FEDERAL 35-114 | PR          |
| 294674      | WELL | PR     | 02/26/2008  | GW         | 077-09500 | VEGA FEDERAL 35-321 | PR          |
| 294675      | WELL | PR     | 02/26/2008  | GW         | 077-09501 | VEGA FEDERAL 35-221 | PR          |

**General Comment:**

[Follow-up inspection from FIR DOC 675001461 dated 12/10/18.](#)  
[Corrective action of posting Nearest access has not completed](#)

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action  |        | Date: |  |

Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | BATTERY                                 |       |            |
| Comment:             | missing nearest access information      |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.b. | Date: | 02/11/2019 |

Emergency Contact Number:

Comment: 911 / Posted Emergency Contact Number 1-800-891-6191

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Plunger Lift                | # 7 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Emission Control Device     | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Gas Meter Run               | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 6 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 8 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |         |        |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
| METHANOL           | 1 | <50 BBLS | STEEL AST |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

|                    |   |          |           |         |        |  |
|--------------------|---|----------|-----------|---------|--------|--|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |  |
| CONDENSATE         | 2 | 400 BBLS | STEEL AST |         | ,      |  |
| Comment:           |   |          |           |         |        |  |
| Corrective Action: |   | Date:    |           |         |        |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

|                    |   |          |                  |         |        |  |
|--------------------|---|----------|------------------|---------|--------|--|
| Contents           | # | Capacity | Type             | Tank ID | SE GPS |  |
| CONDENSATE         | 2 | 400 BBLS | HEATED STEEL AST |         | ,      |  |
| Comment:           |   |          |                  |         |        |  |
| Corrective Action: |   | Date:    |                  |         |        |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|      |          |                     |                     |             |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|

Inspector Name: Wentzel, Dougo

|                    |          |                 |                |          |       |
|--------------------|----------|-----------------|----------------|----------|-------|
| Metal              | Adequate | Walls Sufficent | Base Sufficent | Adequate |       |
| Comment:           |          |                 |                |          |       |
| Corrective Action: |          |                 |                |          | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

| Inspected Facilities  |                                 |       |      |             |           |         |    |               |    |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 294427                          | Type: | WELL | API Number: | 077-09476 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 294670                          | Type: | WELL | API Number: | 077-09496 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 294671                          | Type: | WELL | API Number: | 077-09497 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 294672                          | Type: | WELL | API Number: | 077-09498 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 294673                          | Type: | WELL | API Number: | 077-09499 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 294674                          | Type: | WELL | API Number: | 077-09500 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 294675                          | Type: | WELL | API Number: | 077-09501 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 675001991    | Inspection 675001990 photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742568">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742568</a> |