

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2019

Submitted Date:

02/22/2019

Document Number:

688000268**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 313839 YOUNG, ROB 2A Doc Num: _____

Operator Information:OGCC Operator Number: 76840Name of Operator: SCHNEIDER ENERGY SERVICES INCAddress: P O BOX 889City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

General Comment:

Environmental inspection related to plugging notice 401927555, 2/3/2019. Partially buried produced water tank requires closure under an approved Form 27. Historic crude oil impacted soil at the crude tank battery, separator and produced water tank, see attached photos.

Environmental

Spill/Remediation:

Comment: [Partially buried produced water tank \(PBV\) on location.](#)

Corrective Action: [Submit an eForm 27 for prior approval describing PBV removal and confirmation soil sampling.](#)
[Include plans to remove historic oil impacted soil from separator and tank battery.](#)

Date: 03/08/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____