

Inspection Photos

Loc#334601

Operator: Terra

Inspection Number: 692400704

Inspection Date: 2/20/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry to North.

February 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra GV Loc#334601



Photo#2:
Areas of Location have not been Reclaimed for Interim Reclamation.

February 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra GV Loc#334601



Photo#3:


Sediment migration is occurring from un-stabilized areas of pad. Areas of Pad are rutted where traffic appears to be encroaching in what would be Interim Reclamation areas.

February 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra GV Loc#334601



Photo#4:

Erosion is occurring on Cut Slope with sediment migrating onto Location.

February 20, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra GV Loc#334601