

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/20/2019

Submitted Date:

02/24/2019

Document Number:

692400704**FIELD INSPECTION FORM**

Loc ID 334601	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> 4 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested <b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210964	WELL	PR	02/14/1991	GW	045-06722	EXXON GV 18-23	RI
277713	WELL	PR	03/14/2006	GW	045-10756	BOSLEY SG 321-23	RI
277714	WELL	PR	02/27/2006	GW	045-10757	BOSLEY SG 521-23	RI
277715	WELL	PR	03/11/2006	GW	045-10758	BOSLEY SG 421-23	RI
277716	WELL	PR	03/06/2006	GW	045-10759	BOSLEY SG 21-23	RI
424063	WELL	PR	05/08/2012	GW	045-20827	Bosely SG 11-23	RI
424066	WELL	PR	05/31/2012	GW	045-20828	Bosely GM 524-14	RI
424070	WELL	PR	05/15/2012	GW	045-20829	Bosely SG 432-23	RI
424072	WELL	PR	05/09/2012	GW	045-20830	Bosely SG 422-23	RI
424074	WELL	PR	05/03/2012	GW	045-20831	Bosely SG 332-23	RI
424075	WELL	PR	05/01/2012	GW	045-20832	Bosely GM 314-14	RI
424077	WELL	PR	05/08/2012	GW	045-20833	Bosely SG 22-23	RI
424078	WELL	PR	05/03/2012	GW	045-20834	Bosely SG 631-23	RI
424089	WELL	PR	05/08/2012	GW	045-20835	Bosley SG 322-23	RI
424091	WELL	PR	05/31/2012	GW	045-20836	Bosely GM 514-14	RI
424092	WELL	PR	05/03/2012	OW	045-20837	Bosely SG 532-23	RI
424094	WELL	PR	05/08/2012	GW	045-20838	Bosely SG 311-23	RI
424095	WELL	PR	05/01/2012	GW	045-20839	Bosely GM 414-14	RI
438328	WELL	XX	07/20/2016	LO	045-22485	Strait Bottom Ranch SG 723-24-23-HN1	RI
438329	WELL	XX	07/20/2016	LO	045-22486	Strait Bottom Ranch SG 723-14-23-HN1	RI

**General Comment:**

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

Inspected Facilities				
Facility ID: <u>210964</u>	Type: <u>WELL</u>	API Number: <u>045-06722</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277713</u>	Type: <u>WELL</u>	API Number: <u>045-10756</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277714</u>	Type: <u>WELL</u>	API Number: <u>045-10757</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277715</u>	Type: <u>WELL</u>	API Number: <u>045-10758</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277716</u>	Type: <u>WELL</u>	API Number: <u>045-10759</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424063</u>	Type: <u>WELL</u>	API Number: <u>045-20827</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424066</u>	Type: <u>WELL</u>	API Number: <u>045-20828</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424070</u>	Type: <u>WELL</u>	API Number: <u>045-20829</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424072</u>	Type: <u>WELL</u>	API Number: <u>045-20830</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424074</u>	Type: <u>WELL</u>	API Number: <u>045-20831</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424075</u>	Type: <u>WELL</u>	API Number: <u>045-20832</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424077</u>	Type: <u>WELL</u>	API Number: <u>045-20833</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424078</u>	Type: <u>WELL</u>	API Number: <u>045-20834</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424089</u>	Type: <u>WELL</u>	API Number: <u>045-20835</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424091</u>	Type: <u>WELL</u>	API Number: <u>045-20836</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424092</u>	Type: <u>WELL</u>	API Number: <u>045-20837</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424094</u>	Type: <u>WELL</u>	API Number: <u>045-20838</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>424095</u>	Type: <u>WELL</u>	API Number: <u>045-20839</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>438328</u>	Type: <u>WELL</u>	API Number: <u>045-22485</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

Facility ID:	438329	Type:	WELL	API Number:	045-22486	Status:	XX	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

--

--

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Fail Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass  
 Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

## RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation Fail

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? P

Comment

Two XX Wells on site; 045-22485 & 045-22486 are bonded per the NTO: Procedures for Preset Conductors though Permits for the Wells expired 11/9/18.  
 Areas of Location have not been Reclaimed for Interim Reclamation. Site does not have a Delayed Operations Variance on file.

Corrective Action

There are two CAs in this Section:

1) Refile APDs for XX Wells or Abandon Permits, Plugging & Abandoning Conductors.

2) Submit Interim Reclamation Variance Request per NTO: Interim Reclamation Procedures for Delayed Operations or Conduct Interim Reclamation in Areas no longer needed for use by May 20,2019.

Date 03/25/2019

## Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Areas of Pad are rutted where traffic appears to be encroaching in what would be Interim Reclamation areas; sediment migration is occurring from unstabilized areas of pad. Erosion is occurring on Cut Slope with sediment migrating onto Location.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Stabilization of Pad areas can be conducted within the month; Stabilization of Cut slope will need to be delayed until dry-up.

Date: 03/24/2019

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692400718	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4743475">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4743475</a>