

# Final Reclamation and Stormwater Inspection

February 13, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 306449

Inspection Document #: 674902583

Weld County, CO

NWSE Section 15 T2N R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /2N68W15  
Location ID: 306449



**Photo 1.** Photo taken from the access road looking into the location, facing Northeast. Appears Operator has performed final with no sign of equipment left on site. However it appears the well location is not reflective of the adjacent reference crop areas.



**Photo 2.** Photo taken from the location, facing North. See comments from Photo 1.

Inspection Photos  
Location Name: KERR MCGEE /2N68W15  
Location ID: 306449



**Photo 3.** Photo taken from the location, facing West. See comments from Photo 1.