


**Inspection Photo (s)**  
**Last Dance 12-2**  
**05-045-09416**  
**Inspection # 689303358**



**Location Photo #1**

**Location Photo #2**

**Inspection Photo (s)**  
**Last Dance 12-2**  
**05-045-09416**  
**Inspection # 689303358**



**Location Photo #3**



**Location Photo #4, Stained ground.  
Mechanical condition of casing valve.**

**Inspection Photo (s)**  
**Last Dance 12-2**  
**05-045-09416**  
**Inspection # 689303358**



**Location Photo #5, unused/unmarked flow line riser.**



**Location Photo #6, non legible sign on 500 gallon methanol tank.**

**Inspection Photo (s)**  
**Last Dance 12-2**  
**05-045-09416**  
**Inspection # 689303358**



**Location Photo #7, non legible sign on 200 bbl tank.**



**Location Photo #8, stained ground. Mechanical condition of 2" valve.**