

Inspection Photos

Location Name: CONTINENTAL 1-8

Location ID: 05-103-07908

Inspection: 679703134



Photo 1. Location looking southeast.



Photo 2. Gas leak at flange next to gas meter building.

Inspection Photos
Location Name: CONTINENTAL 1-8
Location ID: 05-103-07908
Inspection: 679703134



Photo 3. Uncapped risers.



Photo 4. Uncapped risers.

Inspection Photos

Location Name: CONTINENTAL 1-8

Location ID: 05-103-07908

Inspection: 679703134



Photo 5. Weeds & vegetation in the blowdown pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources