

Inspection Photos  
Location Name: Sharp #2E  
API: 05-067-06666



Sharp #2E location photo.



Sharp #2E pump jack and well head.

**Inspection Photos**  
**Location Name: Sharp #2E**  
**API: 05-067-06666**



**Lube oil container on secondary containment. Secondary containment is almost full.**



**95 bbl. produced water PBV.**