

Inspection Photos

Location Name: CONTINENTAL 4-8

Location ID: 05-103-08090

Inspection: 679703139



Photo 1. Location looking east.



Photo 2. Unused pipe.



Inspection Photos

Location Name: CONTINENTAL 4-8

Location ID: 05-103-08090

Inspection: 679703139




Photo 3. Sign missing nearest public road.



Photo 4. Weeds on location.



Inspection Photos
Location Name: CONTINENTAL 4-8
Location ID: 05-103-08090
Inspection: 679703139



Photo 5. Weeds in pit #1.



Photo 6. Weeds in pit #2.