

Inspection Photos

Location Name: RANGELY SOUTH FEDERAL 18-3-1-102

Location ID: 05-103-09023

Inspection: 679703154



Photo 1. Location looking west.



Photo 2. Hole in blowdown tank.

Inspection Photos

Location Name: RANGELY SOUTH FEDERAL 18-3-1-102

Location ID: 05-103-09023

Inspection: 679703154



Photo 3. Tank without berm.

