

Inspection Photos

Location Name: RANGELY SOUTH FEDERAL 9-4-1-102

Location ID: 05-103-09026

Inspection: 679703158



Photo 1. Location looking north.



Photo 1. Well head sign missing.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: RANGELY SOUTH FEDERAL 9-4-1-102

Location ID: 05-103-09026

Inspection: 679703158



Photo 3. Tank without label.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources