

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2019

Submitted Date:

02/21/2019

Document Number:

675001977**FIELD INSPECTION FORM**Loc ID 334487 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                                 | Comment                         |
|-----------------|-------|---------------------------------------|---------------------------------|
| Kellerby, Shaun |       | shaun.kellerby@state.co.us            | <a href="#">All Inspections</a> |
| Peicka, Conor   |       | conor.pesicka@state.co.us             | <a href="#">All Inspections</a> |
| Clark, Chris    |       | cogccnotifications@laramie-energy.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 290618      | WELL | PR     | 05/16/2007  | GW         | 077-09287 | NORTH VEGA 26-221 | PR          |
| 291546      | WELL | PR     | 11/13/2012  | GW         | 077-09361 | DELTA 26-231      | PR          |
| 291547      | WELL | PR     | 07/24/2007  | GW         | 077-09360 | DELTA 26-241      | PR          |
| 291548      | WELL | PR     | 07/24/2007  | GW         | 077-09359 | DELTA 26-224      | PR          |
| 291549      | WELL | PR     | 07/24/2007  | GW         | 077-09358 | DELTA 26-141      | PR          |
| 291550      | WELL | PR     | 07/24/2007  | GW         | 077-09357 | DELTA 26-134      | PR          |
| 291551      | WELL | PR     | 07/24/2007  | GW         | 077-09356 | DELTA 26-131      | PR          |
| 291552      | WELL | PR     | 07/24/2007  | GW         | 077-09355 | DELTA 26-124      | SI          |
| 291553      | WELL | PR     | 07/24/2007  | GW         | 077-09354 | DELTA 26-121      | PR          |

**General Comment:**

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action  | L      | Date: |  |

Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | BATTERY  |       |            |
| Comment:             | No Nearest Access posted on location<br>Still lists Deta and other phone numbers on signs that are no longer Laramie's |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.d.  | Date: | 04/22/2019 |
| Type                 | WELLHEAD   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             |  |       |            |
| Corrective Action:   |  | Date: |            |

Emergency Contact Number:

Comment: 911 / 1-800-891-6191

Corrective Action:

Date:

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

|                                   |     |       |                 |
|-----------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>                 |     |       | corrective date |
| Type: Gas Meter Run               | # 1 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Bird Protectors             | # 7 |       |                 |
| Comment:                          |     |       |                 |
| Corrective Action:                |     | Date: |                 |
| Type: Horizontal Heated Separator | # 9 |       |                 |
| Comment:                          |     |       |                 |

|                    |     |       |  |
|--------------------|-----|-------|--|
| Corrective Action: |     | Date: |  |
| Type: Plunger Lift | # 9 |       |  |
| Comment:           |     |       |  |
| Corrective Action: |     | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| METHANOL           | 1 | <50 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 2 | 400 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type             | Tank ID | SE GPS |
|--------------------|---|----------|------------------|---------|--------|
| CONDENSATE         | 2 | 400 BBLS | HEATED STEEL AST |         | ,      |
| Comment:           |   |          |                  |         |        |
| Corrective Action: |   |          |                  |         | Date:  |

Paint

|                 |          |  |
|-----------------|----------|--|
| Condition       | Adequate |  |
| Other (Content) |          |  |

Other (Capacity)

Other (Type)

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |  |
| Comment:           |          |                     |                     |             |  |
| Corrective Action: |          |                     |                     | Date:       |  |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |
|--------------------|--|--|
| Type               |  |  |
| Comment:           |  |  |
| Corrective Action: |  |  |

| Inspected Facilities  |                                 |       |      |             |           |         |    |               |    |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 290618                          | Type: | WELL | API Number: | 077-09287 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291546                          | Type: | WELL | API Number: | 077-09361 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291547                          | Type: | WELL | API Number: | 077-09360 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291548                          | Type: | WELL | API Number: | 077-09359 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291549                          | Type: | WELL | API Number: | 077-09358 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291550                          | Type: | WELL | API Number: | 077-09357 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291551                          | Type: | WELL | API Number: | 077-09356 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 291552                          | Type: | WELL | API Number: | 077-09355 | Status: | PR | Insp. Status: | SI |

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: [Shut in last production shown is is 8/18](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 291553 Type: WELL API Number: 077-09354 Status: PR Insp. Status: PR**Producing Well**Comment: [Well Producing on plunger lift.](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 |                         |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 401948054    | INSPECTION SUBMITTED        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742571">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742571</a> |
| 675001987    | Inspection 675001977 photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742564">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742564</a> |