

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2019

Submitted Date:

02/21/2019

Document Number:

689702683**FIELD INSPECTION FORM**

Loc ID 415180	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 37 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415220	WELL	PR	10/11/2010	GW	045-18996	Story Gulch Unit 8501A-36 B36496	PR
415224	WELL	PR	03/29/2012	GW	045-18997	Story Gulch Unit 8501D-36 B36496	PR
415228	WELL	PR	12/03/2010	GW	045-18998	Story Gulch Unit 8505A-36 B36496	PR
415231	WELL	PR	03/09/2012	GW	045-18999	Story Gulch Unit 8505B-36 B36496	PR
415237	WELL	PR	11/25/2010	GW	045-19001	Story Gulch Unit 8508B-36 B36496	PR
415242	WELL	PR	10/10/2010	GW	045-19002	Story Gulch Unit 8502B-36 B36496	PR
415248	WELL	PR	10/13/2010	GW	045-19003	Story Gulch Unit 8501B-36 B36496	PR
415600	WELL	PR	03/02/2011	GW	045-19113	Story Gulch Unit 8506D-36 B36496	PR
415605	WELL	PR	01/24/2011	GW	045-19114	Story Gulch Unit 8509B-36 B36496	PR
415611	WELL	PR	01/28/2011	GW	045-19115	Story Gulch Unit 8505D-36 B36496	PR
415612	WELL	PR	01/15/2011	GW	045-19116	Story Gulch Unit 8509D-36 B36496	PR
415616	WELL	PR	01/28/2011	GW	045-19117	Story Gulch Unit 8508D-36 B36496	PR
415617	WELL	PR	06/05/2012	GW	045-19118	Story Gulch Unit 8507D-36 B36496	PR
415620	WELL	PR	03/14/2011	GW	045-19119	Story Gulch Unit 8506A-36 B36496	PR

415621	WELL	PR	01/28/2011	GW	045-19120	Story Gulch Unit 8505C-36 B36496	PR
418888	WELL	PR	10/22/2011	GW	045-19818	SGU 8506C-36 B36496	PR
418889	WELL	PR	04/21/2012	GW	045-19819	SGU 8507A-36 B36496	PR
418890	WELL	PR	03/05/2012	GW	045-19820	SGU 8506B-36 B36496	PR
418891	WELL	PR	04/21/2012	GW	045-19821	SGU 8507C-36 B36496	PR
418892	WELL	PR	03/05/2012	GW	045-19822	SGU 8503D-36 B36496	PR
418893	WELL	PR	10/21/2011	GW	045-19823	SGU 8502D-36 B36496	PR
418895	WELL	PR	04/25/2012	GW	045-19824	SGU 8507B-36 B36496	PR
418896	WELL	PR	09/24/2011	GW	045-19825	SGU 8502C-36 B36496	PR
418897	WELL	PR	07/01/2018	GW	045-19826	SGU 8502A-36 B36496	PR
418898	WELL	PR	07/01/2018	GW	045-19827	SGU 8501C-36 B36496	PR
418941	WELL	PR	09/24/2011	GW	045-19837	SGU 8508A-36 B36496	PR
418944	WELL	PR	04/11/2012	GW	045-19839	SGU 8508C-36 B36496	PR
418946	WELL	PR	08/01/2012	GW	045-19840	SGU 8509A-36 B36496	PR
418952	WELL	PR	10/21/2011	GW	045-19845	SGU 8509C-36 B36496	PR
418960	WELL	PR	10/21/2011	GW	045-19851	SGU 8516A-36 B36496	PR
418966	WELL	PR	04/20/2012	GW	045-19852	SGU 8511A-36 B36496	PR

General Comment:[Routine FIU General Field Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign not found for location.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	04/22/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 7		
Comment:	Chemical containers		
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	250 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	415220	Type:	WELL	API Number:	045-18996	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415224	Type:	WELL	API Number:	045-18997	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415228	Type:	WELL	API Number:	045-18998	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415231	Type:	WELL	API Number:	045-18999	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415237	Type:	WELL	API Number:	045-19001	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415242	Type:	WELL	API Number:	045-19002	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415248	Type:	WELL	API Number:	045-19003	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415600	Type:	WELL	API Number:	045-19113	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 415605	Type: WELL	API Number: 045-19114	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 415611	Type: WELL	API Number: 045-19115	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 415612	Type: WELL	API Number: 045-19116	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 415616	Type: WELL	API Number: 045-19117	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 415617	Type: WELL	API Number: 045-19118	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 415620	Type: WELL	API Number: 045-19119	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 415621	Type: WELL	API Number: 045-19120	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 418888	Type: WELL	API Number: 045-19818	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID:	418889	Type:	WELL	API Number:	045-19819	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418890	Type:	WELL	API Number:	045-19820	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418891	Type:	WELL	API Number:	045-19821	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418892	Type:	WELL	API Number:	045-19822	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418893	Type:	WELL	API Number:	045-19823	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418895	Type:	WELL	API Number:	045-19824	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418896	Type:	WELL	API Number:	045-19825	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418897	Type:	WELL	API Number:	045-19826	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	418898	Type:	WELL	API Number:	045-19827	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418941	Type:	WELL	API Number:	045-19837	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418944	Type:	WELL	API Number:	045-19839	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418946	Type:	WELL	API Number:	045-19840	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418952	Type:	WELL	API Number:	045-19845	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418960	Type:	WELL	API Number:	045-19851	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418966	Type:	WELL	API Number:	045-19852	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401947999	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742517
689702684	Inspection 689702683 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4742511