

Inspection Photo (s)
BBC 12A-24
API #05-045-17690
FIR Inspection # 689303402



Location Photo #1



Location Photo #2

Inspection Photo (s)
BBC 12A-24
API #05-045-17690
FIR Inspection # 689303402



Location Photo #3



**Location Photo #4, Stained ground
underneath the scrubber pot.**

Inspection Photo (s)
BBC 12A-24
API #05-045-17690
FIR Inspection # 689303402



**Location Photo #5, stained ground
underneath scrubberpot.**