

# *Inspection Photos*

*API#103-40243*

*Operator: Woosley Oil*

*Inspection Number: 692400643*

*Inspection Date: 2/26/19*





Photo#1:  
Overview of Location to Northwest.

February 26, 2019



Photo#2:  
Debris noted on site.

February 26, 2019



Photo#3:  
Debris noted on site.



Photo#4:  
What may have been posts for electrical installation.

February 26, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Woosley Oil PA API#103-40243