

Interim Reclamation and Stormwater Inspection

February 21, 2019

Operator: NOBLE ENERGY INC- #100322

Location ID: 330539

Inspection Document #: 682404570

Weld County, CO

NWSE Section 18 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SLW GREEN STATE #BB 18-10
Location ID: 330539



Photo 1. Photo taken from the western well location on 12/24/18, facing Southwest. Photo illustrates unmanaged weeds (Russian thistle) throughout the location. Russian thistle was observed well beyond the wellhead into interim reclamation areas and off location. Operator shall control weed debris per Rule 603.f. Also, Operator has failed to stabilize the production area. Wind erosion was observed.



Photo 2. Photo taken from the western well location on 2/21/19, facing Southwest. Operator has failed to perform the previous corrective action.

Inspection Photos
Location Name: SLW GREEN STATE #BB 18-10
Location ID: 330539



Photo 3. Photo taken from the southern well location on 12/24/18, facing East. See comments under Photo 1.



Photo 4. Photo taken from the southern well location on 2/21/19, facing East. See comments under Photo 2.

Inspection Photos

Location Name: SLW GREEN STATE #BB 18-10

Location ID: 330539



Photo 5. Photo taken from the southeastern well location on 12/24/18, facing Northeast. See comments under Photo 1.



Photo 6. Photo taken from the southeastern well location on 2/21/19, facing Northeast. See comments under Photo 2.

Inspection Photos

Location Name: SLW GREEN STATE #BB 18-10

Location ID: 330539



Photo 7. Photo taken from the southeastern well location on 12/24/18, facing North. See comments under Photo 1.



Photo 8. Photo taken from the southeastern well location on 2/21/19, facing North. See comments under Photo 2.