

Inspection Photos
Location Name: THAYER-66N66W /19SESW
Location #: 332500



Photo #1
Thayer 19-34 (05-123-22384) Wellsite
Temporarily Abandoned | TA
Unused Equipment
Orange Decommission tag NOT present



Photo #2
Thayer 19-34 Battery
Shut-down