

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2019

Submitted Date:

03/05/2019

Document Number:

696100363

FIELD INSPECTION FORM

Loc ID 310450 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 16 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@nblenergy.com	All Inspections
		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292937	WELL	SI	06/01/2017	GW	123-26421	COUNTRY 1 29-4	TA

General Comment:

This is a WELL & BATTERY Inspection.
Well is TA.
Battery & ALL equipment is Shut-down.
Follow-up to FIR #689300225 dated 09/26/2017.
1 of 1 Corrective Actions from previous FIR has been addressed.
1.) Unused Equipment around Battery site. Has been removed. See photos #2-3.

2 - Corrective Actions identified on this FIR.
1.) Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See attached photo #1.
Remove unused equipment at wellsite. Comply w/ Rule 603.f.
2.) SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See attached photo #1.
Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).

Location			
Lease Road:			
	Type Access		
	comment: Adequate		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type BATTERY		
	Comment:		
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
	Comment:		
Corrective Action:			Date:
	Type WELLHEAD		
	Comment: SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See attached photo #1.		
Corrective Action:	Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).		Date:
Emergency Contact Number:			
	Comment:		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment around Battery site from previous FIR. Has been removed. See photos #2-3.		
Corrective Action:			Date:
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See attached photo #1.		
Corrective Action:	Remove unused equipment at wellsite. Comply w/ Rule 603.f.		Date: <u>04/04/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:			Date:
Type	SEPARATOR		

Comment:	Chain-link.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Chain-link.		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Chain-link.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tanks VOCs Pilot: OFF Shut-down.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Shares berms w/ crude oil tank.						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.461440,-104.806520	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment: Shares berms w/ produced H2O vault.						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 292937 Type: WELL API Number: 123-26421 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. Well disconnected from flowline.
Form 4 #401433832 indicates TA since 04/25/2017.
SI/TA well per variance Doc #401474555. (NOBLE).

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100364	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4752955