

# Construction and Storm Water Inspection

February 26, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 458932

Inspection Document #: 674902584

Weld County, CO

SESW Section 23 T3N R65W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N65W23

Location ID: 458932



**Photo 1.** Photo taken from the northwestern perimeter of the location, facing South. Photo illustrates a Filtrexx BMP that has been installed around the perimeter of the location. However it appears the Operator has left a gap in the Filtrexx along northwestern perimeter. BMPs are not in proper functioning condition at the time of this inspection.



**Photo 2.** Photo taken from the northwestern perimeter of the location, facing North. Photo illustrates a Filtrexx BMP that has been installed around the perimeter of the location.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N65W23

Location ID: 458932



**Photo 3.** Photo taken from the southwestern perimeter of the location, facing East. See comments from Photo 2.



**Photo 4.** Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 2.

Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N65W23

Location ID: 458932



**Photo 5.** Photo taken from the southeastern perimeter of the location, facing West. See comments from Photo 2.



**Photo 6.** Photo taken from the southeastern perimeter of the location, facing North. See comments from Photo 2.

## Inspection Photos

Location Name: NOBLE ENERGY INC – 100322/3N65W23

Location ID: 458932



**Photo 7.** Photo taken from the northwestern perimeter of the location, facing East. Location is currently under construction.



**Photo 8.** Photo taken from the northern perimeter of the location looking towards the access road under current construction, facing North.