

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/05/2019

Submitted Date:

03/05/2019

Document Number:

689702771

**FIELD INSPECTION FORM**

Loc ID 334722 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

30 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264996	WELL	PR	02/12/2003	GW	045-08975	BORUCH GM 24-12	PR
264997	WELL	PR	02/12/2003	GW	045-08974	BROUCH GM 314-12	PR
278944	WELL	PR	05/01/2006	GW	045-10970	BORUCH GM 514-12	PR
278945	WELL	PR	05/26/2006	GW	045-10969	BORUCH GM 324-12	PR
278946	WELL	PR	05/28/2006	GW	045-10968	BORUCH GM 424-12	PR
435441	WELL	PR	08/04/2014	GW	045-22256	C&C Energy GM 21-13	PR
435442	WELL	PR	10/01/2014	GW	045-22257	C&C Energy GM 323-13	PR
435443	WELL	PR	12/01/2017	GW	045-22258	C&C Energy GM 521-13	PR
435444	WELL	PR	12/01/2017	GW	045-22259	C&C Energy GM 22-13	PR
435445	WELL	PR	12/01/2017	GW	045-22260	C&C Energy GM 421-13	PR
435446	WELL	PR	10/01/2014	GW	045-22261	C&C Energy GM 523-13	PR
435447	WELL	PR	07/19/2014	GW	045-22262	C&C Energy GM 423-13	PR
435448	WELL	PR	10/01/2014	GW	045-22263	C&C Energy GM 411-13	PR
435449	WELL	PR	07/01/2014	OW	045-22264	C&C Energy GM 422-13	PR
435450	WELL	PR	01/01/2018	GW	045-22265	C&C Energy GM 23-13	PR
435451	WELL	PR	08/04/2014	GW	045-22266	C&C Energy GM 522-13	PR
435452	WELL	PR	10/01/2014	GW	045-22267	C&C Energy GM 311-13	PR
435453	WELL	PR	10/01/2014	GW	045-22268	C&C Energy GM 511-13	PR
435454	WELL	PR	08/04/2014	GW	045-22269	C&C Energy GM 321-13	PR
435455	WELL	PR	09/01/2018	GW	045-22270	C&C Energy GM 322-13	PR

435456	WELL	PR	10/01/2014	GW	045-22271	C&C Energy GM 11-13	PR
437429	WELL	PR	12/03/2014	GW	045-22427	C&C Energy GM 544-12	PR
437430	WELL	PR	12/03/2014	GW	045-22428	C&C Energy GM 444-12	PR
437431	WELL	PR	11/04/2014	GW	045-22429	C&C Energy GM 344-12	PR
437443	WELL	SI	09/01/2017	GW	045-22430	C&C Energy GM 44-12	SI
437513	WELL	PR	08/01/2018	GW	045-22433	C&C Energy GM 543-12	PR

**General Comment:**

[Routine FIU General Field Inspection](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical container at wells		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 14		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	264996	Type:	WELL	API Number:	045-08975	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	264997	Type:	WELL	API Number:	045-08974	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	278944	Type:	WELL	API Number:	045-10970	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	278945	Type:	WELL	API Number:	045-10969	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	278946	Type:	WELL	API Number:	045-10968	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	435441	Type:	WELL	API Number:	045-22256	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	435442	Type:	WELL	API Number:	045-22257	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	
Facility ID:	435443	Type:	WELL	API Number:	045-22258	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well							Date:	
Corrective Action:								Date:	

Facility ID: 435444	Type: WELL	API Number: 045-22259	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435445	Type: WELL	API Number: 045-22260	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435446	Type: WELL	API Number: 045-22261	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435447	Type: WELL	API Number: 045-22262	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435448	Type: WELL	API Number: 045-22263	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435449	Type: WELL	API Number: 045-22264	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435450	Type: WELL	API Number: 045-22265	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 435451	Type: WELL	API Number: 045-22266	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: 435452	Type: WELL	API Number: 045-22267	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 435453	Type: WELL	API Number: 045-22268	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 435454	Type: WELL	API Number: 045-22269	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 435455	Type: WELL	API Number: 045-22270	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 435456	Type: WELL	API Number: 045-22271	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 437429	Type: WELL	API Number: 045-22427	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 437430	Type: WELL	API Number: 045-22428	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 437431	Type: WELL	API Number: 045-22429	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:			Date:	

Facility ID: 437443 Type: WELL API Number: 045-22430 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut in since Sep. 2017

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 437513 Type: WELL API Number: 045-22433 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Erosion ril on the northern reclaim area.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 04/06/2019

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702772	Inspection 689702771 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4753202">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4753202</a>