

Inspection Photos

Location Name: STROMBERGER-66N67W /13NWSW

Location #: 310388



Photo #1

Stromberger 13-32 (05-123-26334) Wellsite

Unused Equipment

from prev. FIR




Photo #2

Stromberger 13-32 Wellsite

Unused Equipment - Removed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: STROMBERGER-66N67W /13NWSW

Location #: 310388



Photo #3
Stromberger 13-32 Battery
from prev. FIR



Photo #4
Stromberger 13-32 Battery
Abandoned
Unused Equipment – Gas meter run



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources