

Inspection Photos

Location Name: COLUMBINE SP FED 3-14-4-104

Location ID: 05-103-08566

Inspection: 679703226



Photo 1. Location looking northeast.

Gas leaks



Photo 2. Gas leak #1.

Inspection Photos

Location Name: COLUMBINE SP FED 3-14-4-104

Location ID: 05-103-08566

Inspection: 679703226



Photo 3. Gas leak #2.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources