

Inspection Photos

Location Name: COLUMBINE SP FED 3C-14-4-104

Location ID: 05-103-10445

Inspection: 679703228



Photo 1. Location looking east.



Photo 2. Unused tank.



Inspection Photos

Location Name: COLUMBINE SP FED 3C-14-4-104

Location ID: 05-103-10445

Inspection: 679703228



Photo 3. One unused gas meter building.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources