

PIT STATUS EVALUATION FORM

Facility ID: 115068

Pit Name: AMOCO 23-16

☐ Duplicate Record(s) Pit #

115148



Legend

- Database Pit Location
- Producing Well
- ⊙ Shut In Well
- ⊙ Temp Aban Well
- ⊙ Abandoned Well
- ⊙ Dry & Aban Well
- ⬮ Injection Well
- Other Well Status



1:6,000

0 250 500 750 Feet

Image Source:
USDA National Agricultural Imagery
Program (NAIP), 2006

S.S. PAPADOPOULOS & ASSOCIATES, INC.

COGCC Database Information

Status: NR Owner: GARY-WILLIAMS OIL PRODUCER INC

T: 6S R: 64W Sec: 23 QQ: SESE 6th Meridian

Latitude: 39.507817 Longitude: -104.516336 NAD83

County: Elbert, CO

County Code: 039

Pit Status Evaluation

- ☐ Active ☐ Form 15: Pit Permit _____ Assoc. Well Seq No(s) _____
☐ Other documentation _____
☐ Aerial photo verification _____
- ☒ Closed ☐ Form 27: Remediation Workplan _____
☐ Form 4: Sundry Notice _____
☐ Rule 903a.(2)B _____
☒ Evidence pit(s) existed, no closure docs & well not PR, AC or SI
Well API Seq #(s) 06346 PA 16-7-1988
☒ Other documentation WSIF# 448116 (1-19-1989)
- ☐ Abandoned ☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs ☐ Site Visit
☐ No Site Visit
☐ Add'l Review
- ☐ Unknown

Notes: No pit documents. LIF (1985 & 1987) for Pit ID# 115148 indicate skim tank and 4' diameter culvert with cover.