

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401961942
Date Received:
03/06/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Aaron, Axelson</u>	<u>230-0926</u>	<u>aaxelson@vnrenergy.com</u>
<u>Collett, Shane</u>		<u>scollett@vnrenergy.com</u>
<u>Ghan, Scott</u>	<u>970-744-8128</u>	<u>sghan@vnrenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689303394

Inspection Date: 02/28/2019

FIR Submit Date: 02/28/2019

FIR Status: _____

Inspected Operator Information:

Company Name: VANGUARD OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 416197

Location Name: Werner Number: 44C-23-692 County: GARFIELD

Qtrqtr: SWSE Sec: 23 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.507462 Longitude: -107.630253

FACILITY - API Number: 05-045-00 Facility ID: 416217

Facility Name: Werner Number: 31B-26-692

Qtrqtr: SWSE Sec: 23 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.507462 Longitude: -107.630253

CORRECTIVE ACTIONS:

1 CA# 122813

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 03/04/2019

Response: CA COMPLETED

Date of Completion: 03/01/2019

Fixed and cleaned very small seep on threads.

Operator _____
Comment: _____

COGCC Decision: _____

COGCC Representative: _____

2 CA# 122814

Corrective Action: Comply with 603.f
For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser

Date: 03/29/2019

Response: CA COMPLETED

Date of Completion: 03/01/2019

Operator Comment: Tagged risers that are in service and pressure tested yearly.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron Axelson

Signed: _____

Title: Sr. Production Foreman

Date: 3/6/2019 8:45:53 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401961954	Werner 1
401961955	Werner 2
401961959	Werner 3

Total Attach: 3 Files