

Location Name: Own Resources Operating – Crossland 32-33 – Spill ID 460604

Inspection Date: 1/08/2019




Photo # - 1



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Own Resources Operating – Crossland 32-33 – Spill ID 460604
Inspection Date: 1/08/2019



Photo # - 2

Spill area (ice) view south



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Own Resources Operating – Crossland 32-33 – Spill ID 460604
Inspection Date: 1/08/2019



Photo # - 3

Spill area (ice) and wet soil view south



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Own Resources Operating – Crossland 32-33 – Spill ID 460604
Inspection Date: 1/08/2019



Photo # - 4

Spill area (ice) and wet soil view north



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Own Resources Operating – Crossland 32-33 – Spill ID 460604
Inspection Date: 1/08/2019



Photo # - 5

Spill area (ice) and wet soil view east



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources