

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2019

Submitted Date:

03/06/2019

Document Number:

688000276

FIELD INSPECTION FORM

Loc ID 337088 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10489
Name of Operator: AUGUSTUS ENERGY RESOURCES LLC
Address: 2016 GRAND AVENUE #A
City: BILLINGS State: MT Zip: 59102

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282204	WELL	PR	12/22/2005	GW	125-09791	CROSSLAND 32-33 5N46W	EI
460604	SPILL OR RELEASE	AC	01/09/2019		-	Crossland 32-33	EI

General Comment:

[Environmental inspection related to Spill ID 460604.](#)

Inspected Facilities

Facility ID: 282204 Type: WELL API Number: 125-09791 Status: PR Insp. Status: EI

Facility ID: 460604 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: COGCC mapped the spill area on 1/08/2019 using GPS. COGCC spill map is attached to this inspection. Soil samples were not collected at the time of the spill due to freezing conditions.

Corrective Action: Collect a minimum of three soil samples from the spill area for pH, EC and SAR laboratory analysis. Collect a background soil sample for comparison to the spill area sampes and Table 910-1. Submit the results on a supplemental eForm 19.

Date: 03/29/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000277	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754116
688000278	COGCC Spill GPS Map	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4754117