

Inspection Photos
Location Name: McLAUGHLIN SENIOR 40
Location ID: 05-103-40159
Inspection: 679703261



Photo 1. Location looking east.



Photo 2. Pump jack (no motor).

Inspection Photos

Location Name: McLAUGHLIN SENIOR 40

Location ID: 05-103-40159

Inspection: 679703261



Photo 3. Electric panel not closed.



Photo 4. Wellhead sign that does not belong to this well.

