

Inspection Photo (s)
State of Colorado KP 422-9
API # 05-045-22219
FIR Inspection # 689303454



Location Photo #1



Location Photo #2



Inspection Photo (s)
State of Colorado KP 422-9
API # 05-045-22219
FIR Inspection # 689303454



Location Photo #2, Area of debris, near separators.



Location Photo #3, Area of debris, East side of location by the wellheads.

Inspection Photo (s)
State of Colorado KP 422-9
API # 05-045-22219
FIR Inspection # 689303454



Location Photo #5, Area of debris, North end of location.



Location Photo #6, Area of debris, North end of location.