

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401956324
Date Received:
03/01/2019

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Aaron, Axelson</u>	<u>230-0926</u>	<u>aaxelson@vnrenergy.com</u>
<u>Ghan, Scott</u>	<u>970-744-8128</u>	<u>sghan@vnrenergy.com</u>
<u>Collett, Shane</u>		<u>scollett@vnrenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689303235
Inspection Date: 02/13/2019 FIR Submit Date: 02/13/2019 FIR Status: _____

Inspected Operator Information:

Company Name: VANGUARD OPERATING LLC Company Number: 10531
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 335157

Location Name: SPECIALTY-66S92W Number: 21SWSE County: GARFIELD
Qtrqr: SWSE Sec: 21 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.508320 Longitude: -107.668290

FACILITY - API Number: 05-045-00 Facility ID: 292949

Facility Name: SPECIALTY Number: 43C-21-692
Qtrqr: SWSE Sec: 21 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.508320 Longitude: -107.668290

CORRECTIVE ACTIONS:

1 ☒ CA# 122492

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 03/15/2019

Response: CA COMPLETED

Date of Completion: 02/16/2019

Replaced cracked line. Photo attached.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the FORM 4/FIRR, acknowledges that the Oil and Gas Conservation Commission has received the Notice.
A field inspection will be conducted to evaluate compliance.

2  CA# 122493

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e.

Date: 02/16/2019

Response: CA COMPLETED

Date of Completion: 02/16/2019

Operator
Comment:

Removed and disposed impacted soil in lined containment. Photo attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approval/passing of the FORM 4/FIRR, acknowledges that the Oil and Gas Conservation Commission has received the Notice.
A field inspection will be conducted to evaluate compliance.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron Axelson

Signed: _____

Title: Sr. Production Foreman

Date: 3/1/2019 5:36:05 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401956324	FIR RESOLUTION SUBMITTED
401956326	Specilaty 5 Pic 1
401956327	Specilaty 5 Pic 2

Total Attach: 3 Files