

Inspection Photos
Location Name: FILLY 44-13
API #: 05-071-07478
Insp. Doc. # 695100304



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: FILLY 44-13
API #: 05-071-07478
Insp. Doc. # 695100304



PHOTO 3: TRASH IN PIT



PHOTO 4: TRASH IN PIT

Inspection Photos
Location Name: FILLY 44-13
API #: 05-071-07478
Insp. Doc. # 695100304



PHOTO 5: IMPACTED SOIL NEAR SEPARATOR DRAIN