

Inspection Photos

Location Name: McLAUGHLIN SR 6-33

Location ID: 05-103-05500

Inspection: 679703258



Photo 1. Location looking east.



Photo 2. Container of labeled transmission fluid at pump jack.



Inspection Photos

Location Name: McLAUGHLIN SR 6-33

Location ID: 05-103-05500

Inspection: 679703258



Photo 3. Oil staining on ground at wellhead.



Photo 4. Oily substance 10' from wellhead.



Inspection Photos

Location Name: McLAUGHLIN SR 6-33

Location ID: 05-103-05500

Inspection: 679703258



Photo 5. Power panel open.

