

Inspection Photos
Location Name: PARK MOUNTAIN 13-18
Location ID: 05-103-09773
Inspection: 679703277



Photo 1. Location looking west.



Photo 2. Sign missing nearest public rd, CR 109.

Inspection Photos
Location Name: PARK MOUNTAIN 13-18
Location ID: 05-103-09773
Inspection: 679703277



Photo 3. Dead weeds on berm.



Photo 4. Unused containers.