

Inspection Photos
Location Name: NORTHER 23-6
API #: 05-071-09439
Insp. Doc. # 695100306



PHOTO 1: LOCATION

PHOTO 2: LOCATION SIGN

Inspection Photos
Location Name: NORTHER 23-6
API #: 05-071-09439
Insp. Doc. # 695100306




PHOTO 3: CALIBRATION REPORT IS PAST DUE. IT HAS BEEN OVER ONE YEAR SINCE LAST CALIBRATION.