

Inspection Photos

Location Name: ANDERSON-66N66W /10SWNE

Location #: 305912



Photo #1

Anderson 32-10 (05-123-23661) Wellsite

Temporarily Abandoned | TA

Unused Equipment



Photo #2

Anderson 31-10, 32-10, 42-10 Battery site

