

Inspection Photos

Location Name: ANDERSON-66N66W /10NENE

Location #: 319434



Photo #1

Anderson 1-10 (05-123-11265) Wellsite

Plugged & Abandoned | PA

Reclamation in process



Photo #2

Anderson 1-10 Abandoned Battery site

Reclamation in process

Unused Equipment

Gas meter run



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources