

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2019

Submitted Date:

03/05/2019

Document Number:

696100363

FIELD INSPECTION FORMLoc ID 310450 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292937	WELL	SI	06/01/2017	GW	123-26421	COUNTRY 1 29-4	TA

General Comment:

This is a WELL & BATTERY Inspection.

Well is TA.

Battery & ALL equipment is Shut-down.

Follow-up to FIR #689300225 dated 09/26/2017.

1 of 1 Corrective Actions from previous FIR has been addressed.

1.) Unused Equipment around Battery site. Has been removed. See photos #2-3.

2 - Corrective Actions identified on this FIR.

1.) Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See attached photo #1.

Remove unused equipment at wellsite. Comply w/ Rule 603.f.

2.) SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See attached photo #1.

Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See attached photo #1.		
Corrective Action:	Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).	Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment around Battery site from previous FIR. Has been removed. See photos #2-3.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment at wellsite. Refer to Rule 603.f for guidance (30 Days). See attached photo #1.		
Corrective Action:	Remove unused equipment at wellsite. Comply w/ Rule 603.f.	Date:	04/04/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type	SEPARATOR		

Comment:	Chain-link.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain-link.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Chain-link.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Bradenhead appears plumbed to surface.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tanks VOCs Pilot: OFF Shut-down.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	53 Bbls.

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:				Shares berms w/ crude oil tank.		
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.461440,-104.806520	
Comment:						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:				Shares berms w/ produced H2O vault.		
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
Flaring:						
Type						
Comment:						
Corrective Action:				Date:		

Inspected FacilitiesFacility ID: 292937 Type: WELL API Number: 123-26421 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA. Well disconnected from flowline.
Form 4 #401433832 indicates TA since 04/25/2017.
SI/TA well per variance Doc #401474555. (NOBLE).

Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401960767	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4752960
696100364	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4752955