

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401970475

Date Received:

03/12/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10669

Name of Operator: NICKEL ROAD OPERATING LLC

Address: 600 17TH STREET #610S

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

JENNIFER LIND

Phone

303-406-1117

Email

JENNIFER.LIND@NICKELROADOPERATING.COM

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404468

Inspection Date: 01/28/2019

FIR Submit Date: 01/29/2019

FIR Status: _____

Inspected Operator Information:

Company Name: NICKEL ROAD OPERATING LLC

Company Number: 10669

Address: 600 17TH STREET #610S

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 454899

Location Name: DRAKE PAD Number: _____ County: _____

Qtrqr: NWSE Sec: 12 Twp: 7N Range: 67W Meridian: 6

Latitude: 40.588176 Longitude: -104.838093

FACILITY - API Number: 05-123-00 Facility ID: 454899

Facility Name: DRAKE PAD Number: _____

Qtrqr: NWSE Sec: 12 Twp: 7N Range: 67W Meridian: 6

Latitude: 40.588176 Longitude: -104.838093

CORRECTIVE ACTIONS:

1 CA# 122083

Corrective Action: Per Rule 805.c., Operator shall control fugitive dust caused by their operations. The corrective date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 01/28/2019

Response: CA COMPLETED

Date of Completion: 01/29/2019

Operator Comment: Following receipt of inspection report on 1/29/19, Nickel Road immediately had dirt work contractor onsite contact water truck company to ensure a water-truck was available on-call should pad and weather conditions warrant use. Water truck will remain on call throughout operations at the location. Additionally, the pad location surface was gravelled following the date of this inspection (gravelling complete on 2/8/19) and vehicle tracking control was installed (vehicle tracking install complete on 2/11/19) both assisting in the mitigation of dust conditions. Finally, Nickel Road has plans in place to hydroseed all slopes for stabilization and weed prevention purposes

during the Spring, 2019 growing season. Nickel Road has maintained compliance since the 1/28/19 inspection and will continue to maintain compliance with Rule 805.c.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: FIR Resolution submitted in response to Doc #682404468. See detailed response on "Corrective Actions & Responses" tab.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: JENNIFER LIND

Signed: _____

Title: REG & ENV MANAGER

Date: 3/12/2019 3:35:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files