

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/07/2019

Submitted Date:

03/07/2019

Document Number:

696100407**FIELD INSPECTION FORM**Loc ID 305320 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276532	WELL	SI	09/01/2015	GW	123-22797	WEBER 6-13	SI

General Comment:

This is a WELL & BATTERY Inspection.

Well is SI & LOTO.

Battery & ALL equipment is Shut-down.

1 - Corrective Action identified.

1.) SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.

Install orange decommission tag at wellsite to comply with Doc #401474555 (NOBLE).

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	SI/TA well per variance Doc #401474555. Orange decommission tag for SI/TA status not present at wellsite. See photo #1.		
Corrective Action:	Install orange decommission tag at wellsite. Comply with Doc #401474555 (NOBLE).	Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced H2O vault capacity label is fading. Consider replacing.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 580px;" type="text"/>	
Corrective Action:	<input style="width: 580px;" type="text"/>	Date: <input style="width: 100px;" type="text"/>

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Surrounded by metal berms.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 1	
Comment:	Controls crude oil tanks VOCs Pilots: OFF Shut-down.	
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	ECD scrubber	
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Bradenhead appears plumbed to surface.	
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.516489,-104.817566
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berms w/ produced H2O vault.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity) 48 Bbls.	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Shares berms w/ crude oil tank.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 276532 Type: WELL API Number: 123-22797 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Observed well SI & LOTO.
COGCC records indicate SI since 09/2015.
Orange decommission tag for SI/TA status not present at wellsite. No current MIT on record.
SI/TA well per variance Doc #401474555. (NOBLE).

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401965128	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755925
696100408	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4755924