

# Inspection Photos

Operator: Kinder Morgan  
Location/API #: 083-06633  
Date: 2/13/2019



Photo 1. View of the eastern project area from the well pad entrance facing northward. Area appears to have been recently seeded.



Photo 2. View of the southern project area from the well pad entrance facing westward.



Photo 3. View of soil stockpile within the southwestern project area.



Photo 4. View of excavation area within the southwestern project area. Straw wattles are in place.