

Final Reclamation and Stormwater Inspection

March 1, 2019

Operator: PDC ENERGY INC # 69175

Location ID: 331522

Inspection Document #: 674902639

Weld County, CO

NWNW Section 28 T2N R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: PDC ENERGY INC/2N64W28

Location ID: 331522



Photo 1. Photo taken from the access road looking towards the location, facing West. The access road remains on location.



Photo 2. Photo taken from the location, facing West. Appears Operator has removed all equipment from location however no evidence of reclamation activities has been observed.

Inspection Photos
Location Name: PDC ENERGY INC/2N64W28
Location ID: 331522



Photo 3. Photo taken from the location looking back towards the access road, facing East. See comments from Photos 1 and 2.



Photo 4. Photo taken from the location, facing West. See comments from Photo 2.

Inspection Photos
Location Name: PDC ENERGY INC/2N64W28
Location ID: 331522



Photo 5. Photo taken from the location, facing East. See comments from Photos 1 and 2.



Photo 6. Photo taken from the location, facing Northeast. See comments from Photo 2.